

Wolf Creek Property Owners Association System Update

April

- Water system routine checks and chlorination monitoring
- Started putting together a Cross Connection Control Plan
- USA Leak Detectors found several leaks
- Negative coli form sample

May:

- Meters were read
- Leaks were repaired on Winding Rd, Cottonwood Meadows & Green Meadows
- Negative VOC, Gross alpha, radium & coliform sample
- Water system was routinely checked and monitored for chlorine levels
- Found buried valves during leak repairs
- A new valve was installed at VH4/GM-1; can now isolate lower VH
- Leak repairs account for huge reduction in source pumping and electricity
- Saw class reduced fuel loading and hazard trees on association properties
- The head gate/fish screen are continually monitored